Burch



Repeats Not Shown to Scale.

Nimbus Veil 1009673

Meets or exceeds all ACT® Standards

Made in the USA High Performance Fabric Soil and Stain Repellent



*ACT® Registered Certification Marks

Fabric Specifications

| Content | 25% Rayon 24% Polyester 21% Post Consumer Recycled Polyester 20% Nylon 10% Post Industrial Recycled Polyester |
|-----------------|---|
| Finish | Soil and Stain Repellent |
| Backing | Acrylic |
| Weight | 16.0 oz. per linear yd |
| Width | 54" |
| Roll Size | 60 yards |
| Ends/Picks | Ends: 77 per inch Picks: 178 per inch |
| Repeat | H - 13.75 " V - 18.0" |
| Directional | Yes |
| Railroaded | No |
| Made in the USA | Yes |

Performance Characteristics

| Abrasion Resistance ASTM D4157 | 60,000 double rubs* |
|-----------------------------------|--------------------------------------|
| Brush Pill Brush + SPONGE | 3 |
| Tensile Strength ASTM D5034 | Warp: 205.0 lbs. Fill: 204.0 lbs. |
| Tear Strength ASTM D2261 | Warp: 57.0 lbs. Fill: 39.0 lbs. |
| Seam Slippage ASTM D4034 | Warp: 62.0 lbs. Fill: 89.0 lbs. |
| Colorfastness to Crocking AATCC 8 | Dry: 4.0 Wet: 4.0 |
| Colorfastness to Light AATCC 16 | Hours: 40.0 Class: 4.0 |
| Flammability** | |
| CAL TB 117-2013 | Passes |
| NFPA 260 | Class 1 |
| UFAC | Class 1 |
| | |

Additional Attributes

| High Performance | Yes | | |
|---|-----|--|--|
| Recommended Cleaning | | | |
| Please refer to Detailed Cleaning Instructions. | | | |

Although we try hard to make sure colors on our site are accurate, actual colors may vary. Please order samples prior to making a purchase.

 $Final\ determination\ of\ the\ suitability\ of\ this\ product\ for\ an\ application\ rests\ with\ the\ user.$

* Abrasion test results exceeding ACT Performance Guidelines are not an indicator of product lifespan. Multiple factors affect fabric durability and appearance retention.

** This term and any corresponding data refer to the typical performance in the specific tests indicated and should not be construed to imply the behavior of this or any other material under actual fire conditions.