

TEST REPORT

Mechanical & Hardgoods Laboratory

Report No: TH10036/2019

Page: of

Date: JAN. 15, 2019

CGPC AMERICA CORPORATION

The following merchandise was submitted and identified by the applicant as:

Style/Item No:

BANDWIDTH

Country of Origin:

Taiwan

We have tested the submitted sample(s) as requested and the following results were obtained:

For compliance with California Technical Bulletin 117-2013 Test Requested:

Requirements, Test Procedure and Apparatus for Testing the Smolder

Resistance of Materials Used in Upholstered Furniture – Section 1

Cover Fabric Test

Test Result:

Please refer to the following page(s).

--- See Next Page ---

Signed for and on behalf of SGS Taiwan Ltd.

Luke Lee

Asst. Supervisor

Testing Place: No. 9, 14th Rd., Taichung Ind. Park, Taichung City 40755, Taiwan

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of client's instruction, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced, except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested No.127, Wu Kung Road, New Taipei Industrial Park, New Taipei City, Taiwan /新北市新北產業園區五工路 127 號



TEST REPORT

Mechanical & Hardgoods Laboratory

Report No: TH10036/2019

Page: of

SEC. 1 Cover Fabric Test

Criteria	Test 1	Test 2	Test 3
1.4.1a) The mock-up test specimen continues to smolder after	No	No	No
the 45 minute test duration;			
1.4.1b) A vertical char length of more than 1.8 inches (45	No	No	No
mm) develops on the cover fabric.			
1.4.1c) The mock-up test specimen transitions to open	No	No	No
flaming.			
1.4.2. The cover fabric passes the test if three initial mock-up	Yes	Yes	Yes
specimens pass the test, i.e., the cigarettes burn their full			
length and the mock-ups are no longer smoldering.			
1.4.3. If more than one initial specimen fails, the cover fabric	N/A	N/A	N/A
fails the test.			
1.4.4. If any one of the three initial specimens fails, repeat the	N/A	N/A	N/A
test on additional three specimens.			0
1.4.5. If all three additional specimens pass the test, the cover	N/A	N/A	N/A
fabric passes the test. If any one of the additional three			
specimens fails, the cover fabric fails the test.			

N/A = Not Applicable

Conclusion:

The submitted sample(s) **complies** with the requirements of Section 1.4 for Cover Fabric Test of California Technical Bulletin 117-2013.

--End of Report--

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of client's instruction, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced, except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested

SGS Taiwan Ltd.

No.127, Wu Kung Road, New Taipei Industrial Park, New Taipei City, Taiwan /新北市新北產業園區五工路 127 號 to (886-2) 2299-3279

f (886-2) 2299-2920

www.tw.sgs.com



Test Report

Number: TWNC00761137

Date : Jan 19, 2019

Sample Description:

Item : BANDWIDTH

: Taiwan

: CGPC America Corporation

Test Conducted:

As requested by the applicant, for details please refer to attached pages.

Authorized By:

On behalf of Intertek Testing Services

Taiwan Limited

Carol Peng

General Manager

Signed by:

Thomas Chou Manager



homas Chou

Page 1 of 3

11492 台北市內湖區瑞光路 423 號 8 樓 Tel: (+886-2) 6602-2888 · 2797-8885 Fax: (+886-2) 6602-2405





Number: TWNC00761137

Test Conducted:

1. Flammability Test

As per NFPA 260 - 2003 6.1 cover fabric test.

Cover Fabric Classification

Class I: Cover fabric shall meet the criteria of (A) and (B)

- (A) When subjected to the cover fabric test, a specimen shall show no evidence of ignition of any test assembly
- (B) The vertical char in any of the three specimens shall not exceed 45 mm

Class II: Cover fabric that do not meet Class I criteria shall be designated as Class II

Specimen Number	<u>Ignition</u>	<u>Char Length (mm)</u>
1.	No	7 (#)
2.	No	8 (#)
3.	No	5 (#)

Classification = Class I

Remark: # = Cigarette did not get burn totally

Page 2 of 3





Number: TWNC00761137

End of Report

Except where explicitly agreed in writing, all work and services performed by Intertek is subject to our standard Terms and Conditions which can be obtained at our website: http://www.intertek-twn.com/terms/. Intertek's responsibility and liability are limited to the terms and conditions of the agreement.

This report is made solely on the basis of your instructions and / or information and materials supplied by you and provide no warranty on the tested sample(s) be truly representative of the sample source. The report is not intended to be a recommendation for any particular course of action, you are responsible for acting as you see fit on the basis of the report results. Intertek is under no obligation to refer to or report upon any facts or circumstances which are outside the specific instructions received and accepts no responsibility to any parties whatsoever, following the issue of the report, for any matters arising outside the agreed scope of the works. This report does not discharge or release you from your legal obligations and duties to any other person. You are the only one authorized to permit copying or distribution of this report (and then only in its entirety). Any such third parties to whom this report may be circulated rely on the content of the report solely at their own risk.





8F., No. 423, Ruiguang Rd., Neihu District, Taipei 11492, Taiwan, R.O.C. 全國公證檢驗股份有限公司 11492 台北市內湖區瑞光路 423 號 8 樓 Tel: (+886-2) 6602-2888 · 2797-8885 Fax: (+886-2) 6602-2405

