

Burch

UFAC Quality Assurance Lab Test Report

Date:	05/22/2015
Material #:	Livewire
Material Name:	NA
Sales Order:	NA
Reference Material:	F-0225620-01
Contents:	100% Poly
Weight oz/Linear yd:	10.688

Section 1: Cover Fabric Test

Length of char in inches

Specimen # 1	0.75
Specimen # 2	0.75
Specimen # 3	0.75

Char Length: Class I (X) Class II ()

If the char measures 1.75 inches or less, Passing results are categorized as Class I. If the char measures more than 1.75 inches, the result is failing, Failing results are categorized as Class II

QA Lab Manager:	<i>Barbara Grant</i>
Date:	05/22/2015
Telephone #	828-893-4382

Burch

NFPA 260 Certificate Quality Assurance Lab Test Report

Date:	05/22/2015
Material #:	Livewire
Material Name:	NA
Sales Order:	NA
Reference Material:	F-0225620-01
Contents:	100% Poly
Weight oz/Linear yd:	10.688

Section 1: Cover Fabric Test

Length of char in inches

Specimen # 1	0.75
Specimen # 2	0.75
Specimen # 3	0.75

Char Length: Class I (X) Class II ()

If the char measures 1.75 inches or less, Passing results are categorized as Class I. If the char measures more than 1.75 inches, the result is failing, Failing results are categorized as Class II

QA Lab Manager:	<i>Barbara Grant</i>
Date:	05/22/2015
Telephone #	828-893-4382

Burch

TB Cal. 117-2013 Quality Assurance Lab Test Report

Date:	05/22/2015
Material #:	Livewire
Material Name:	NA
Sales Order:	NA
Reference Material:	F-0225620-01
Contents:	100% Poly
Weight oz/Linear yd:	10.688

Section 1: Cover Fabric Test

Length of char in inches

Specimen # 1	0.75
Specimen # 2	0.75
Specimen # 3	0.75

Char Length: Pass (X) Fail ()

If the char measures 1.8 inches or less, the result is passing.

If the char measures more than 1.8 inches, the result is failing

45 Minute Smolder Resistance: Pass (X) Fail ()

QA Lab Manager:	<i>Barbara Grant</i>
Date:	05/22/2015
Telephone #	828-893-4382