

How to Clean Reverie

Nanotex® Fabric

Prompt cleaning is always recommended.

Recommended cleaning steps are listed by type of stain. For best results follow cleaning steps in order.

Recommended Care and Cleaning Guide:

1. Blot up liquids on the surface with a clean, soft towel.
2. Prepare a cleaning solution (see recommendations below).
3. Apply solution sparingly with a misting spray bottle. Work into affected area by lightly scrubbing the area with a soft-bristle brush. Make sure to rub from outside of stain inward so as not to spread the stain.
4. Rinse area thoroughly to remove all soap residue, as residue will attract dirt.

Repeat steps 3-4 as needed. Use a low-heat hair dryer or allow fabric to air-dry.

Cleaning Solution Recommendations:

Mix ½ teaspoon Tide® to 1 cup water for:

Beer	Chewing Gum	Crayon	Ink (ballpoint)	Lipstick	Soy Sauce	Wax (candle)
Betadine	Chocolate	Grape Jelly	Iron Rust	Mayo	Suntan Lotion	Wine
Butter	Coffee	Grape Juice	Italian Dressing	Milk	Tea	
Charcoal	Cola	Gravy	Ketchup	Pencil Marks	Tomato Juice	

Tips and Tricks:

- Make sure to clean away excess mess first.
- Use as little solution as possible.
- Brush stains inward, not outward.
- Use a clean white rag or paper towel (without design or printing).
- Always use a dry section of the rag for soaking up liquids.
- Be sure to rinse thoroughly, possibly multiple times.

NANOTEX®
BY CRYPTON

Cleaning information is offered for general guidance and is not a guarantee. The use of certain cleaning agents can be harmful to the surface appearance and lifespan of a product. Burch Fabrics assumes no responsibility for damage to a product resulting from lack of cleaning, improper cleaning or the misuse of cleaning agents. Certain clothing and accessory dyes (such as those used on denim jeans) may migrate to materials and cause permanent damage. Burch Fabrics cannot be held responsible for dye transfer caused by external contaminants.
