



**BURCH
FABRICS**

**TB Cal. 117-2013
Quality Assurance Lab Test Report**

Date: 01/29/2015
Material #: F-0225278-01
Material Name: Lattice
Sales Order: 15319973-10
Reference Material: NA
Contents: 100% Polyester

Weight oz/Linear yd: 13.168

Section 1: Cover Fabric Test

Length of char in inches

Specimen # 1 0.25
Specimen # 2 0.25
Specimen # 3 0.063

Char Length: Pass (X) Fail ()

If the char measures 1.8 inches or less, the result is passing.

If the char measures more than 1.8 inches, the result is failing

45 Minute Smolder Resistance: Pass (X) Fail ()

QA Lab Manager: *Barbara Grant*
Date: 01/29/2015
Telephone # 828-893-4382



NFPA 260 Certificate Quality Assurance Lab Test Report

Date:	01/29/2015
Material #:	F-0225278-01
Material Name:	Lattice
Sales Order:	15319973-10
Reference Material:	NA
Contents:	100% Polyester

Weight oz/Linear yd: 13.168

Section 1: Cover Fabric Test

Length of char in inches

Specimen # 1	0.25
Specimen # 2	0.25
Specimen # 3	0.063

Char Length: Class I (X) Class II ()

If the char measures 1.75 inches or less, Passing results are categorized as Class I. If the char measures more than 1.75 inches, the result is failing, Failing results are categorized as Class II

QA Lab Manager:	<i>Barbara Grant</i>
Date:	01/29/2015
Telephone #	828-893-4382



UFAC
Quality Assurance Lab Test Report

Date:	01/29/2015
Material #:	F-0225278-01
Material Name:	Lattice
Sales Order:	15319973-10
Reference Material:	NA
Contents:	100% Polyester

Weight oz/Linear yd: 13.168

Section 1: Cover Fabric Test

Length of char in inches

Specimen # 1	0.25
Specimen # 2	0.25
Specimen # 3	0.063

Char Length: Class I (X) Class II ()

If the char measures 1.75 inches or less, Passing results are categorized as Class I. If the char measures more than 1.75 inches, the result is failing, Failing results are categorized as Class II

QA Lab Manager:	<i>Barbara Grant</i>
Date:	01/29/2015
Telephone #	828-893-4382