# Burch

## TB Cal. 117-2013 Quality Assurance Lab Test Report

Test Date:

08/23/2018

Material #:

Material Name:

8/27/18tlp

Customer ID:

Capri

Reference Material:

Contents:

100.00% OLEFIN

Wgt oz/Linear yd: 12.96

### Section 1: Cover Fabric Test

Length of Char in Inches

Specimen #1

0.750 Inch

Specimen #2

0.750 Inch

Specimen #3

0.750 Inch

Char Length:

Pass

If the char measures 1.8 inches or less, the result is passing. If the char measures more than 1.8 inches, the result is failing.

45 Minute Smolder

Resistance:

Pass

QA Lab Manager:

Barbara Grant

01/13/2022

Telephone #: 828-893-4382

# Burch

## NFPA 260 Certificate Quality Assurance Lab Test Report

Test Date:

08/23/2018

Material #:

Material Name:

8/27/18tlp

Customer ID:

Capri

Reference Material:

Contents:

100.00% OLEFIN

Wgt oz/Linear yd: 12.96

#### Section 1: Cover Fabric Test

#### Length of Char in Inches

Specimen #1

0.750 Inch

Specimen #2

0.750 Inch

Specimen #3

0.750 Inch

Char Length:

Class I

If the char measures 1.75 inches or less, passing results are categorizeed as Class I. If the char measures more than 1.75 inches, the result is failing, Failing results are categorized as Class II

QA Lab Manager:

Barbara Grant

Date:

01/13/2022

Telephone #: 828-893-4382

## Burch

## **UFAC** Quality Assurance Lab Test Report

Test Date:

08/23/2018

Material #:

Material Name:

8/27/18tlp

Customer ID:

Capri

Reference Material:

Contents:

100.00% OLEFIN

Wgt oz/Linear yd:

12.96

#### Section 1: Cover Fabric Test

Length of Char in Inches

Specimen #1

0.750 Inch

Specimen #2

0.750 Inch

Specimen #3

0.750 Inch

Char Length:

Class I

If the char measures 1.75 inches or less, passing results are categorizeed as Class I. If the char measures more than 1.75 inches, the result is failing, Failing results are categorized as Class II

QA Lab Manager:

Barbara Grant

01/13/2022

Telephone #: 828-893-4382