

ISO: 9001 Certified

# TB Cal. 117-2013 Quality Assurance Lab Test Report

Date:

12/08/2016

Material #:

Material Name:

CHALET

Reference Material:

Contents:

55.60% OLEFIN, 28.01% POLY, 16.39% PRE-CRCOTN

Wgt oz/Linear yd:

29.408

### Section 1: Cover Fabric Test

Length of Char in Inches

Specimen #1

0.500 Inch

Specimen #2

0.250 Inch

Specimen #3

0.500 Inch

Char Length:

**Pass** 

If the char measures 1.8 inches or less, the result is passing. If the char measures more than 1.8 inches, the result is failing.

45 Minute Smolder

Resistance:

Pass

QA Lab Manager: Barbara Grant

Date:

12/08/2016

Telephone #:

828-893-4382



ISO: 9001 Certified

### NFPA 260 Certificate Quality Assurance Lab Test Report

Date:

12/08/2016

Material #:

Material Name:

CHALET

Reference Material:

Contents:

55.60% OLEFIN, 28.01% POLY, 16.39% PRE-CRCOTN

Wgt oz/Linear yd:

29.408

#### Section 1: Cover Fabric Test

#### Length of Char in Inches

Specimen #1 0.500 Inch Specimen #2 0.250 Inch Specimen #3 0.500 Inch Char Length: Class I

If the char measures 1.75 inches or less, passing results are categorizeed as Class I. If the char measures more than 1.75 inches, the result is failing, Failing results are categorized as Class II

QA Lab Manager: Barbara Grant

Date:

12/08/2016

Telephone #:

828-893-4382



ISO: 9001 Certified

# UFAC Quality Assurance Lab Test Report

**Date:** 12/08/2016

Material #:

Material Name: CHALET

Reference Material:

Contents: 55.60% OLEFIN, 28.01% POLY, 16.39% PRE-CRCOTN

Wgt oz/Linear yd: 29.408

### Section 1: Cover Fabric Test

#### Length of Char in Inches

Specimen #1 0.500 Inch
Specimen #2 0.250 Inch
Specimen #3 0.500 Inch
Char Length: Class I

If the char measures 1.75 inches or less, passing results are categorizeed as Class I. If the char measures more than 1.75 inches, the result is failing, Failing results are categorized as Class II

QA Lab Manager: Barbara Grant

A hab Manager. Barbara Gran

Date: 12/08/2016

Telephone #: 828-893-4382