

## *TB Cal. 117-2013 Quality Assurance Lab Test Report*

Date: 07/24/2017  
Material #: --  
Material Name: CIRCA  
Reference Material: F-0220345-01  
Contents: 73.64% POLY, 26.36% COTTON  
Wgt oz/Linear yd: 13.024

### *Section 1: Cover Fabric Test*

---

	Length of Char in Inches
Specimen #1	0.750 Inch
Specimen #2	0.750 Inch
Specimen #3	0.750 Inch
Char Length:	Pass

If the char measures 1.8 inches or less, the result is passing.  
If the char measures more than 1.8 inches, the result is failing.

45 Minute Smolder  
Resistance: Pass

QA Lab Manager:	Barbara Grant
Date:	07/24/2017
Telephone #:	828-893-4382

# Burch

## *NFPA 260 Certificate Quality Assurance Lab Test Report*

Date: 07/24/2017  
Material #: --  
Material Name: CIRCA  
Reference Material: F-0220345-01  
Contents: 73.64% POLY, 26.36% COTTON  
Wgt oz/Linear yd: 13.024

### *Section 1: Cover Fabric Test*

---

	Length of Char in Inches
Specimen #1	0.750 Inch
Specimen #2	0.750 Inch
Specimen #3	0.750 Inch
Char Length:	Class I

If the char measures 1.75 inches or less, passing results are categorized as Class I. If the char measures more than 1.75 inches, the result is failing, Failing results are categorized as Class II

QA Lab Manager:	Barbara Grant
Date:	07/24/2017
Telephone #:	828-893-4382

# Burch

## *UFAC Quality Assurance Lab Test Report*

Date: 07/24/2017  
Material #: --  
Material Name: CIRCA  
Reference Material: F-0220345-01  
Contents: 73.64% POLY, 26.36% COTTON  
Wgt oz/Linear yd: 13.024

### *Section 1: Cover Fabric Test*

---

	Length of Char in Inches
Specimen #1	0.750 Inch
Specimen #2	0.750 Inch
Specimen #3	0.750 Inch
Char Length:	Class I

If the char measures 1.75 inches or less, passing results are categorized as Class I. If the char measures more than 1.75 inches, the result is failing, Failing results are categorized as Class II

QA Lab Manager:	Barbara Grant
Date:	07/24/2017
Telephone #:	828-893-4382