



ISO: 9001 Certified

***TB Cal. 117-2013
Quality Assurance Lab Test Report***

Date: 08/17/2016
Material #: --
Material Name: FAST TRACK
Reference Material:
Contents: 65.01% PIRPOLY, 34.99% PCRPOLY
Wgt oz/Linear yd: 11.136

Section 1: Cover Fabric Test

Length of Char in Inches

Specimen #1 0.500 Inch
Specimen #2 0.500 Inch
Specimen #3 0.500 Inch
Char Length: Pass

If the char measures 1.8 inches or less, the result is passing.
If the char measures more than 1.8 inches, the result is failing.

**45 Minute Smolder
Resistance:** Pass

QA Lab Manager:	Barbara Grant
Date:	08/17/2016
Telephone #:	828-893-4382