

# Burch

ISO: 9001 Certified

## ***TB Cal. 117-2013 Quality Assurance Lab Test Report***

Test Date: 08/08/2022  
Material #:  
Material Name:  
Customer ID: Ibiza  
Reference Material:  
Contents: 100.00% POLY (UV)  
Wgt oz/Linear yd: 26.176

### ***Section 1: Cover Fabric Test***

---

	Length of Char in Inches
Specimen #1	0.688 Inch
Specimen #2	0.813 Inch
Specimen #3	0.813 Inch
Char Length:	Pass

If the char measures 1.8 inches or less, the result is passing.  
If the char measures more than 1.8 inches, the result is failing.

45 Minute Smolder  
Resistance: Pass

QA Lab Manager:	Barbara Grant
Date:	10/18/2022
Telephone #:	828-893-4382

# Burch

ISO: 9001 Certified

## ***NFPA 260 Certificate Quality Assurance Lab Test Report***

Test Date: 08/08/2022  
Material #:  
Material Name:  
Customer ID: Ibiza  
Reference Material:  
Contents: 100.00% POLY(UV)  
Wgt oz/Linear yd: 26.176

### ***Section 1: Cover Fabric Test***

---

	Length of Char in Inches
Specimen #1	0.688 Inch
Specimen #2	0.813 Inch
Specimen #3	0.813 Inch
Char Length:	Class I

If the char measures 1.75 inches or less, passing results are categorized as Class I. If the char measures more than 1.75 inches, the result is failing, Failing results are categorized as Class II

QA Lab Manager:	Barbara Grant
Date:	10/18/2022
Telephone #:	828-893-4382

# Burch

ISO: 9001 Certified

## **UFAC** **Quality Assurance Lab Test Report**

Test Date: 08/08/2022  
Material #:  
Material Name:  
Customer ID: Ibiza  
Reference Material:  
Contents: 100.00% POLY (UV)  
Wgt oz/Linear yd: 26.176

### **Section 1: Cover Fabric Test**

---

	Length of Char in Inches
Specimen #1	0.688 Inch
Specimen #2	0.813 Inch
Specimen #3	0.813 Inch
Char Length:	Class I

If the char measures 1.75 inches or less, passing results are categorized as Class I. If the char measures more than 1.75 inches, the result is failing, Failing results are categorized as Class II

QA Lab Manager:	Barbara Grant
Date:	10/18/2022
Telephone #:	828-893-4382