

Burch

TB Cal. 117-2013 Quality Assurance Lab Test Report

Test Date: 01/18/2021
Material #:
Material Name: Rio
Customer ID:
Reference Material:
Contents: 88.41% POLY, 11.59% PCRPOLY
Wgt oz/Linear yd: 12.752

Section 1: Cover Fabric Test

	Length of Char in Inches
Specimen #1	0.500 Inch
Specimen #2	0.500 Inch
Specimen #3	0.500 Inch
Char Length:	Pass

If the char measures 1.8 inches or less, the result is passing.
If the char measures more than 1.8 inches, the result is failing.

**45 Minute Smolder
Resistance:** Pass

QA Lab Manager:	Barbara Grant
Date:	09/30/2021
Telephone #:	828-893-4382

Burch

NFPA 260 Certificate Quality Assurance Lab Test Report

Test Date: 01/18/2021
Material #:
Material Name: Rio
Customer ID:
Reference Material:
Contents: 88.41% POLY, 11.59% PCRPOLY
Wgt oz/Linear yd: 12.752

Section 1: Cover Fabric Test

	Length of Char in Inches
Specimen #1	0.500 Inch
Specimen #2	0.500 Inch
Specimen #3	0.500 Inch
Char Length:	Class I

If the char measures 1.75 inches or less, passing results are categorized as Class I. If the char measures more than 1.75 inches, the result is failing, Failing results are categorized as Class II

QA Lab Manager:	Barbara Grant
Date:	09/30/2021
Telephone #:	828-893-4382

Burch

UFAC

Quality Assurance Lab Test Report

Test Date: 01/18/2021
Material #:
Material Name: Rio
Customer ID:
Reference Material:
Contents: 88.41% POLY, 11.59% PCRPOLY
Wgt oz/Linear yd: 12.752

Section 1: Cover Fabric Test

	Length of Char in Inches
Specimen #1	0.500 Inch
Specimen #2	0.500 Inch
Specimen #3	0.500 Inch
Char Length:	Class I

If the char measures 1.75 inches or less, passing results are categorized as Class I. If the char measures more than 1.75 inches, the result is failing, Failing results are categorized as Class II

QA Lab Manager:	Barbara Grant
Date:	09/30/2021
Telephone #:	828-893-4382